

## Super Mini Digital Multimeter with Rubber Holster



- ▶ AC Voltage: 200/500V+/-1.8%
- ▶ DC Voltage: 200m/2000m/20/200/500V+/-0.5%
- ▶ DC Current: 2m/20m/200mA+/-1.0%
- ▶ Resistance: 200/2000/20K/200K/2M+/-0.8%
- ▶ Diode Test: Tests Current 1.6mA Max, Test Voltage 3V Max
- ▶ Display: 3 1/2 Digit LCD, Max Reading 1999
- ▶ Continuity Buzzer
- ▶ Battery Test
- ▶ IEC 1010-1 CAT II 500V
- ▶ Power Source: 12 VOLT
- ▶ Dimensions: 1.89" X 3.94" X 1.02"
- ▶ Weight: 1.6 oz.
- ▶ Accessories: Holster, Test Leads, Battery & Instruction Manual
- ▶ Blister Packed

**FITS IN YOUR SHIRT POCKET**

Cat. No.	Description	Qty
57050	Multimeter	1
51052	Replacement Test Leads	1

## Pocket Digital Multimeter with Vinyl Case



- ▶ AC Voltage: 200/450V+/-1.2%
- ▶ DC Voltage: 2/20/200/450V+/-0.5%
- ▶ DC Current: 200mA+/-1.2%
- ▶ Resistance: 2000/20K/200K/2M/20M+/-1.0%
- ▶ Diode Test: Tests Current 1.6mA Max, Test Voltage 3V Max
- ▶ Continuity Buzzer
- ▶ Polarity: Automatic (-) Negative Polarity Indication
- ▶ Zero Adjustment: Automatic
- ▶ Overload Protection: 200mA and 0.2 Amp Fuse Protection
- ▶ Display: 3-1/2 Digit LCD, Max Reading 1999
- ▶ Power Source: 12V A23 EL12 Button Cell Battery
- ▶ Dimensions: 2.24" X 4.27" X .55"
- ▶ Weight: 2.5 oz.
- ▶ Accessories: Case, Test Leads, Battery & Instruction Manual
- ▶ Blister Packed

Cat. No.	Description	Inner Box Qty	Case Qty
57060	Multimeter	10	100

## Digital Multimeter with Rubber Holster



- ▶ AC Voltage: 200/600V+/-1.2%
- ▶ DC Voltage: 200m/2/20/200V+/-0.5% 600V+/-0.8%
- ▶ DC Current: 200u/2m/20m/200mA +/-1% 10A +/-3%
- ▶ Resistance: 200/2K/20K/200K/2M +/-0.8%
- ▶ Diode Test: Tests Current 1.0mA
- ▶ Audible Continuity Test
- ▶ Data Hold
- ▶ Back Lit
- ▶ Overload Protection
- ▶ Power Source: 6F22(9V) X 1
- ▶ Fuse 200mA/250V
- ▶ IEC 61010-1 CAT II 600V
- ▶ Dimensions: 1.25" X 2.72" X 5.44"
- ▶ Weight: 9 oz.
- ▶ Accessories: Rubber Holster, Test Leads, Battery & Instruction Manual
- ▶ Blister Packed

Cat. No.	Description	Qty
57030	Multimeter	1
51054	Replacement Test Leads	1

## Digital Multimeter & Temperature Probe with Rubber Holster



- ▶ AC Voltage: 200/600V+/-1.2%
- ▶ DC Voltage: 200mV/2V/20V/200V+/-0.5%, 600V+/-0.8%
- ▶ DC Current: 2mA/20mA/200mA+/-1%, 10A+/-3%
- ▶ Resistance: 200/2K/20K/200K/2M+/-0.8%
- ▶ Temperature: 1° to 752°F (-17° to 400°C) +/-1%+2°C, 754°C to 1382°F (401° to 750° C) +/-2%+2°C
- ▶ Diode Test
- ▶ Audible Continuity Test
- ▶ Data Hold
- ▶ Overload Protection
- ▶ Power Source: 6F22(9V) X 1
- ▶ Fuse 200mA/250V
- ▶ IEC 61010-1 CAT II 600V
- ▶ Dimensions: 1.25" X 2.72" X 5.44"
- ▶ Weight: 9 oz.
- ▶ Accessories: Rubber Holster, Test Leads, Battery & Instruction Manual
- ▶ Blister Packed

Cat. No.	Description	Qty
57040	Multimeter	1
51054	Replacement Test Leads	1