



Cat III TRMS Auto-Ranging Digital Multimeter W/PC Interface



Santoprene is over-molded on the outer surface for comfort

- DC Voltage: 400mV/4V/40V/400V \pm 0.5%, 100V \pm 0.8%
- AC Voltage: 4V/40V/400V \pm 0.8%, 700V \pm 1.2%
- DC Current: 400 μ A/4000 μ A/40mA /400mA \pm 1.2%, 10A \pm 2.0%
- AC Current: 400 μ /4000 μ /40m /400mA \pm 1.5%, 10A \pm 3.0%
- Resistance: 400 /4k /40K /400k /4M Ω \pm 1.0%, 40M Ω \pm 2.0%
- Capacitance: 50nF \pm 5.0% 500nF/5 μ F/50 μ F 100 μ F \pm 3.0%
- Frequency: 5Hz/50Hz/500Hz/5KHz/ \pm 0.2%
- Temperature: 4° to 1832°F (-20° to 1000°C) \pm 3.0% + 2°
- Duty: 0.1% ~ 99.99%
- Auto power off
- Continuity Test
- Date hold
- Diode Test
- RS232 Standard interface
- Display 3999 counts
- Auto range and manual range
- Relative measurement
- Back light
- True RMS value

Cat. No.	Case Qty
57074	10

CAT III Auto-Ranging 400A AC Slimline Clamp



- Voltage DC 600V with basic accuracy \pm (0.5%+5d)
- Voltage AC 600V with basic accuracy \pm (0.8%+5d)
- Current AC 400V with basic accuracy \pm (2.50%+6d)
- Resistance 20M Ω with basic accuracy \pm (1.0%+4d)
- Continuity buzzer sound at 300 Ω
- Diode test current 0.3mA; Open circuit voltage 1.5V
- Accessories: test leads, carrying case, 2-AAA 1.5V batteries
- Dimensions: (LxWxH) 8-1/16" x 2-3/4" x 1-1/2"
- Weight: 7oz.
- 2000 LCD display counts
- Decimal Point Readings
- Display with backlight
- Data hold
- Max hold
- Auto power off
- Low battery indication

Cat. No.	Case Qty
57250	50

400A Digital Clamp Meter with Temperature Probe



- AC Current: 200A \pm 1.5%, 400A \pm 2.0%
- AC Voltage: 600V \pm 1.5%
- DC Voltage: 600V \pm 1.0%
- Resistance: 2000K \pm 1.0%
- Temperature Range: -4°F to 500°F (-20°C to 260°C) +/-3%, F° & C° Selectable
- Easy Single Rotary Switch for any Function Selection
- Jaw Opening To 1.06"
- Continuity Buzzer
- Data Hold for all Functions
- Overload Protection for all Ranges
- Diode Test: Tests Current 1.4mA Max, Test Voltage 2.8V Max
- Display: 3-1/2 Digit LCD, Max Reading 1999
- Power Source: 9 Volt Battery
- Dimensions: 8.07" X 1.73" X 1.57"
- Weight: 7.0 Ounces
- Accessories: Carrying Case, Test Leads, Temperature Probe, Battery & Instruction Manual

Cat. No.	Description	Qty
57200	400A Clamp Meter	1
51056	Replacement Test Leads	1